

# Certificate of Acknowledgment

NORMAN NOBLE, INC.

ISO Class 7

Gown Room

Has been tested in accordance with the specifications and guidelines referenced in ISO 14644-1:2015(E), ISO 14644-3:2005(E), TEST-RP-CC006.3. This certificate does not imply full compliance to any or all of the standards listed herein as there are disciplines exceeding the scope of testing provided by Clean Air Testing, Inc. All details are outlined in the corresponding test report #2304A287

**Airborne Non-Viable Particle Measurement**  
**Airflow Measurement**  
**Room Pressurization Measurement**  
**HEPA Filter Installation Leak Test**

Pass  
N/A  
N/A  
Not Tested

**Airborne Viable Particle Measurement**  
 Bacterial  Fungal  
**Surface Viable Particle Measurement**  
 Bacterial  Fungal

Not Tested  
Not Tested



Julie Weidemann

4/26/2023



**Quality Testing Services by Quality People**

37709 Schoolcraft Road, Livonia, MI 48150  
ph: (734) 522-1533 • fx: (734) 522-1534  
catestinginc.com • info@catestinginc.com

# Certificate of Acknowledgment

NORMAN NOBLE, INC.

ISO Class 7

Walk-in Pass Thru

Has been tested in accordance with the specifications and guidelines referenced in ISO 14644-1:2015(E), ISO 14644-3:2005(E), IEST-RP-CC006.3. This certificate does not imply full compliance to any or all of the standards listed herein as there are disciplines exceeding the scope of testing provided by Clean Air Testing, Inc. All details are outlined in the corresponding test report #2304A287

Airborne Non-Viable Particle Measurement  
Airflow Measurement  
Room Pressurization Measurement  
HEPA Filter Installation Leak Test

Pass  
N/A  
N/A  
Not Tested

Airborne Viable Particle Measurement  
 Bacterial  Fungal  
Surface Viable Particle Measurement  
 Bacterial  Fungal

Not Tested  
Not Tested



Julie Weidemann

4/26/2023



Quality Testing Services by Quality People

37709 Schoolcraft Road, Livonia, MI 48150  
ph: (734) 522-1533 • fx: (734) 522-1534  
catestinginc.com • info@catestinginc.com

# Certificate of Acknowledgment

NORMAN NOBLE, INC.

ISO Class 7

Cleanroom

Has been tested in accordance with the specifications and guidelines referenced in ISO 14644-1:2015(E), ISO 14644-3:2005(E), TEST-RP-CC006.3. This certificate does not imply full compliance to any or all of the standards listed herein as there are disciplines exceeding the scope of testing provided by Clean Air Testing, Inc. All details are outlined in the corresponding test report #2504A287

Airborne Non-Viable Particle Measurement

Airflow Measurement

Room Pressurization Measurement

HEPA Filter Installation Leak Test

Pass

N/A

N/A

Not Tested

Airborne Viable Particle Measurement

Bacterial  Fungal

Surface Viable Particle Measurement

Bacterial  Fungal

Not Tested

Not Tested



Julie Weidemann

4/26/2023



Quality Testing Services by Quality People

37709 Schoolcraft Road, Livonia, MI 48150  
ph: (734) 522-1533 • fx: (734) 522-1534  
catestinginc.com • info@catestinginc.com